

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2015 Levee Inspection Results

Reclamation District No. 2058 Pescadero

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2015 Levee Inspection Results

Reclamation District No. 2058 Pescadero

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.58
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	05/12/2015 - 05/12/2015			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Greg Pombo RD2058			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	6		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD2058_01_s _ 2013_6						
Action/Comments							
Inspector Comments: The LMA has current flood fight training.							

No Photos

LM Start		Rating **	A	Issue No.	7	
LM End		Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Emergency Supplies & Equipment				°	°
					°	°
DWR ID	DWR_RD2058_01_s _ 2013_7					
Action/Comments						
Inspector Comments: Flood fight supplies are available on-site at the office.						

No Photos

LM Start		Rating **	A	Issue No.	9	
LM End		Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Operations & Maintenance Manuals				°	°
					°	°
DWR ID	DWR_RD2058_01_s _ 2013_9					
Action/Comments						
Inspector Comments: The O&M Manual is available at the district office.						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	0.14	Rating **	M	Issue No.	562
LM End	0.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.803271 °	37.803271 °
				-121.419533 °	-121.419533 °
DWR ID	DWR_RD2058_01_s_2015_562				
Action/Comments					
Debris					
Inspector Comments: Debris contains asphalt.					

Photo 1 of 1 : SP_2015_RD2058_111_562_20150518_00832.jpg



View of the concrete and asphalt debris on the waterside levee slope.

LM Start	0.23	Rating **	A/W	Issue No.	4
LM End	0.23	Issue Type +	Ob	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.804351 °	37.804351 °
				-121.418433 °	-121.418433 °
DWR ID	DWR_RD2058_01_f_2013_4				
Action/Comments					
Environmental Requirements.					
Inspector Comments: Wild rose on the levee. This area is riparian rabbit habitat.					

Photo 1 of 1 : SP_2015_RD2058_111_4_20150317_00003.jpg



View of the wild rose habitat for the brush rabbit.

LM Start	0.50	Rating **	M	Issue No.	301
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.802932 °	37.802932 °
				-121.414652 °	-121.414652 °
DWR ID	DWR_RD2058_01_s_2014_301				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : SP_2015_RD2058_111_301_20150317_00018.jpg



View of the trees at the landside levee toe obstructing visibility and access.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	0.73	Rating **	M	Issue No.	975
LM End	0.73	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.801792 °	37.801792 °
				-121.410921 °	-121.410921 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45843 DS_ID:22700 EP_NO: 5055 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Excessive oil leakage. FIELD_STRUCT_DESC: 16-inch steel stormdrain pipe through levee 3.8 feet below crown. Pump on concrete sump on landside. Siphon breaker under protective cover on the waterward slope (Permit No. 5055, 1666). FS Date: 05/12/2015					

No Photos

LM Start	1.23	Rating **	M	Issue No.	976
LM End	1.23	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.802249 °	37.802249 °
				-121.402183 °	-121.402183 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45847 DS_ID:22693 EP_NO: 10426 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Crossing needs to be marked. FIELD_STRUCT_DESC: 33-inch steel sewer pipe through levee 17.0 feet below crown. Manholes visible along Delta Ave but no other indicators visible at levee (Permit No. 10426, 1975). FS Date: 05/12/2015					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	1.24	Rating **	U	Issue No.	977
LM End	1.24	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.802301 °	37.802301 °
				-121.401977 °	-121.401977 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45850 DS_ID:22694 EP_NO: 11546 Repair Type: Urgent Crossing Status: Found UCIP Comments: Erosion on west side of pipe at W/S toe. FIELD_STRUCT_DESC: 18-inch steel stormdrain pipe through the levee 2-feet below the crown. Pump in ditch on the landward side. Siphon breaker on waterside shoulder. Electrical service pole at the landward toe. Permit No. 11546, 1976. FS Date: 05/13/2015					

No Photos

LM Start	1.25	Rating **	M	Issue No.	563
LM End	1.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.802399 °	37.802399 °
				-121.401558 °	-121.401558 °
DWR ID	DWR_RD2058_01_s_2015_563				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP_2015_RD2058_111_563_20150518_00833.jpg



View of the vegetation on the landside levee slope.

LM Start	1.70	Rating **	U	Issue No.	961
LM End	1.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.804333 °	37.804615 °
				-121.393657 °	-121.392588 °
DWR ID	DWR_RD2058_01_s_2012_961				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : SP_2015_RD2058_111_961_20150317_00019.jpg



View if the overgrown vegetation on the waterside slope to be removed.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	1.82	Rating **	U	Issue No.	11
LM End	1.82	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.804785 °	37.804785 °
				-121.391524 °	-121.391524 °
DWR ID	DWR_RD2058_01_f_2013_11				
Action/Comments					
Material					
Inspector Comments: Pile of concrete contains rebar on landside slope obstructing visibility and access.					

Photo 1 of 1 : SP_2015_RD2058_111_11_20150317_00004.jpg



View of the concrete with rebar placed on the landside slope.

LM Start	2.12	Rating **	M	Issue No.	1
LM End	2.12	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.803769 °	37.803769 °
				-121.386341 °	-121.386341 °
DWR ID	DWR_RD2058_01_s_2015_1				
Action/Comments					
Inspector Comments: 08/26/2014: No significant change observed. 08/28/2013: No significant change observed. 07/31/2012: Site was visited on 07/26/2012. No significant change observed. A new vertical pipe was installed and concrete blocks left on the site. Dense vegetation is visible at the site. No signs of new leaks or spill from the siphon breaker. 09/02/2011: Site was not visited due to the time limit. 09/22/2010: No significant change observed. Vegetation downstream, upstream and on the lower slope of the site have been recently sprayed. These areas were also fenced off during the site visit, making it difficult for us to examine the condition of the lower slope. Possible leak or spill from the siphon breaker is creating notches along the slope and developing into a headward erosion. If the problem continues, it will erode the slope and fully expose the pipe to outside elements. 07/23/2009: A possible leak or spill from a siphon breaker is eroding the slope and developing into a headward erosion; a portion of the buried pipe is exposed; the lower slope seems to be lined with chunks of concrete debris or other rock material. [2014 Site ID:RD2058U01RM1.78]					

Photo 1 of 1 : SP_2015_RD2058_111_1_20150317_00001.jpg



Direct view of the site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	2.14	Rating **	M	Issue No.	978
LM End	2.14	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.803886 °	37.803886 °
				-121.386271 °	-121.386271 °
DWR ID					

No Photos

Action/Comments					
Inspector Comments: FS_ID:45867 DS_ID:22706 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Leaky and damaged siphon breaker on waterside shoulder. FIELD_STRUCT_DESC: 16-inch steel stormdrain pipe 8.0-feet below the crown. Siphon Breaker on waterward shoulder. Pump on concrete sump on landside. Originally included in the 1964 O&M manual, SJR 10, March 1964. FS Date: 05/13/2015					

LM Start	2.24	Rating **	M	Issue No.	12
LM End	2.30	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.803375 °	37.803136 °
				-121.384196 °	-121.383078 °
DWR ID	DWR_RD2058_01_f_2013_12				
Action/Comments					
Ditch					

Photo 1 of 1 : SP_2015_RD2058_111_12_20150317_00005.jpg



View of the ditch at the landside levee toe.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	2.39	Rating **	A/W	Issue No.	16
LM End	2.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.802782 °	37.802782 °
				-121.381413 °	-121.381413 °
DWR ID	DWR_RD2058_01_s _ 2012_16				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry growing on landside toe.					

Photo 1 of 1 : SP_2015_RD2058_111_16_20150317_00007.jpg



03/28/2012 Large elderberry bush on landside slope.

LM Start	2.61	Rating **	A/W	Issue No.	63
LM End	2.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801962 °	37.801962 °
				-121.377684 °	-121.377684 °
DWR ID	DWR_RD2058_01_s _ 2012_63				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on waterside slope.					

Photo 1 of 1 : SP_2015_RD2058_111_63_20150317_00017.jpg



03/28/2012 Large elderberry bush located on waterward slope.

LM Start	2.63	Rating **	A/W	Issue No.	64
LM End	2.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801876 °	37.801876 °
				-121.377291 °	-121.377291 °
DWR ID	DWR_RD2058_01_s _ 2012_64				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	2.64	Rating **	A/W	Issue No.	65
LM End	2.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801823 °	37.801823 °
				-121.377068 °	-121.377068 °
DWR ID	DWR_RD2058_01_s _ 2012_65				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	2.72	Rating **	A/W	Issue No.	66
LM End	2.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801497 °	37.801497 °
				-121.375586 °	-121.375586 °
DWR ID	DWR_RD2058_01_s _ 2012_66				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	3.37	Rating **	A/W	Issue No.	27
LM End	3.37	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.796421 °	37.796421 °
				-121.366254 °	-121.366254 °
DWR ID	DWR_RD2058_01_s _ 2012_27				
Action/Comments					
Pipe					
Inspector Comments: Drainage discharge.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	3.53	Rating **	A/W	Issue No.	68
LM End	3.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.794396 °	37.794396 °
				-121.364944 °	-121.364944 °
DWR ID	DWR_RD2058_01_s _ 2012_68				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	3.72	Rating **	M	Issue No.	974
LM End	3.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.791856 °	37.791856 °
				-121.363514 °	-121.363514 °
DWR ID	DWR_RD2058_01_s _ 2012_974				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Flagged bushes obstructing visibility and access.					

No Photos

LM Start	3.80	Rating **	A/W	Issue No.	20
LM End	3.80	Issue Type +	Ob	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.790807 °	37.790807 °
				-121.362905 °	-121.362905 °
DWR ID	DWR_RD2058_01_s _ 2012_20				
Action/Comments					
Environmental Requirements.					
Inspector Comments: Revegetation site.					

Photo 1 of 1 : SP_2015_RD2058_111_20_20150317_00008.jpg



11/08/2011 Revegetation site, cannot trim or cut vegetation in this area.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	3.91	Rating **	M	Issue No.	22
LM End	3.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789434 °	37.789434 °
				-121.361721 °	-121.361721 °
DWR ID	DWR_RD2058_01_s _ 2014_22				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : SP_2015_RD2058_111_22_20150317_00009.jpg



View of the tall vegetation on the landside levee slope and toe.

LM Start	3.96	Rating **	M	Issue No.	26
LM End	3.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789128 °	37.789128 °
				-121.361042 °	-121.361042 °
DWR ID	DWR_RD2058_01_s _ 2012_26				
Action/Comments					
Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on landside hinge point.					

Photo 1 of 1 : SP_2015_RD2058_111_26_20150317_00010.jpg



Elderberry bushes on landside slope.

LM Start	3.97	Rating **	A/W	Issue No.	69
LM End	3.97	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789062 °	37.789062 °
				-121.360848 °	-121.360848 °
DWR ID	DWR_RD2058_01_s _ 2012_69				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	4.31	Rating **	A/W	Issue No.	71
LM End	4.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789794 °	37.789794 °
				-121.354883 °	-121.354883 °
DWR ID	DWR_RD2058_01_s _ 2012_71				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

LM Start	4.45	Rating **	M	Issue No.	2
LM End	4.45	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.789810 °	37.789810 °
				-121.352490 °	-121.352490 °
DWR ID	DWR_RD2058_01_s _ 2015_2				
Action/Comments					
Inspector Comments: 08/26/2014: No significant change observed. 08/28/2013: No significant change observed. 07/26/2012: The site has been visited, and no significant change has been observed. 09/02/2011: This site was not visited due to the time limit. 09/22/2010: No significant change observed. Minor pocket erosions are lined at the lower bank. Two large Oak and Willow trees are on mid-slope and bench. The remaining bench was re-measured and found to be approximately 10 feet. There was no indication of active erosion on site during the site visit. 08/05/2010: Recommended for annual assessment and monitoring of the site during flood events, per CLRO. 07/23/2009: No major change observed since last visit; site is a 200-ft. long near-vertical berm erosion; recommend annual assessment and monitoring of the erosion site, per CLRO CES Evaluation 2008 Report; Site # is the same site previously reported as RM4.0,LM4.51; previously rated "U". 09/10/2008: Two large trees (2-3' DBH) with partial roots exposed. 2007: Visited site 03/13/2007. [2014 Site ID:RD2058U01RM3.97]					

Photo 1 of 1 : SP_2015_RD2058_111_2_20150317_00002.jpg



Direct view of the erosion near a tree.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	4.77	Rating **	U	Issue No.	15
LM End	4.77	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.785862 °	37.785862 °
				-121.350303 °	-121.350303 °
DWR ID	DWR_RD2058_01_f_2013_15				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: The erosion has about a 3 foot vertical cut at the waterside levee toe.					

Photo 1 of 1 : SP_2015_RD2058_111_15_20150317_00006.jpg



View of the erosion at the waterside levee toe.

LM Start	4.91	Rating **	M	Issue No.	564
LM End	4.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.784378 °	37.784378 °
				-121.348562 °	-121.348562 °
DWR ID	DWR_RD2058_01_s_2015_564				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP_2015_RD2058_111_564_20150518_00834.jpg



View of the vegetation on the landside levee slope.

LM Start	5.10	Rating **	U	Issue No.	29
LM End	5.10	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.783102 °	37.783102 °
				-121.345682 °	-121.345682 °
DWR ID	DWR_RD2058_01_s_2012_29				
Action/Comments					
Ramp Inspector Comments: New ramp construction connecting dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.					

Photo 1 of 3 : SP_2015_RD2058_111_29_20150317_00011.jpg



11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	5.10	Rating **	U	Issue No.	29 (cont)
LM End	5.10	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.783102 °	37.783102 °
				-121.345682 °	-121.345682 °
DWR ID	DWR_RD2058_01_s _ 2012_29				
Action/Comments					
Ramp Inspector Comments: New ramp construction connecting dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.					

Photo 2 of 3 : SP_2015_RD2058_111_29_20150317_00012.jpg



Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

LM Start	5.10	Rating **	U	Issue No.	29 (cont)
LM End	5.10	Issue Type +	En	Location *	LS

Photo 3 of 3 : SP_2015_RD2058_111_29_20150317_00013.jpg



11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

LM Start	5.29	Rating **	U	Issue No.	30
LM End	5.29	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.782268 °	37.782268 °
				-121.342257 °	-121.342257 °
DWR ID	DWR_RD2058_01_s _ 2012_30				
Action/Comments					
Ramp					
Inspector Comments: Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.					

Photo 1 of 3 : SP_2015_RD2058_111_30_20150317_00014.jpg



11/08/2011 Photo shows existing middle ramp to the levee which has been raised.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	5.29	Rating **	U	Issue No.	30 (cont)
LM End	5.29	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.782268 °	37.782268 °
				-121.342257 °	-121.342257 °
DWR ID	DWR_RD2058_01_s _ 2012_30				
Action/Comments					
Ramp					
Inspector Comments: Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.					

Photo 2 of 3 : SP_2015_RD2058_111_30_20150317_00015.jpg



Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

LM Start	5.29	Rating **	U	Issue No.	30 (cont)
LM End	5.29	Issue Type +	En	Location *	LS

Photo 3 of 3 : SP_2015_RD2058_111_30_20150317_00016.jpg



11/08/2011 Photo shows view from the levee looking to the left of the middle ramp.

LM Start	6.58	Rating **	M	Issue No.	979
LM End	6.58	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770158 °	37.770158 °
				-121.329430 °	-121.329430 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45871 DS_ID:22701 EP_NO: 13262 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Owner needs to install signs at crossing.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	05/12/2015 05/12/2015	Maksim Khashchuk

LM Start	6.58	Rating **	M	Issue No.	980
LM End	6.58	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770159 °	37.770159 °
				-121.329426 °	-121.329426 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45768 DS_ID:25077 EP_NO: 13262 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Owner needs to install signs at crossing. FIELD_STRUCT_DESC: 2 of 3: 4-inch communication conduit encased in concrete through levee 3.0 feet below crown. Sign on both banks of levee. Manhole on both sides of Manthey Rd at utility crossing. (Permit No. 13262, 1981) FS Date: 05/13/2015					

No Photos

LM Start	6.58	Rating **	M	Issue No.	981
LM End	6.58	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770158 °	37.770158 °
				-121.329430 °	-121.329430 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:45769 DS_ID:25078 EP_NO: 13262 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Owner needs to install sign at crossing. FIELD_STRUCT_DESC: 3 of 3: 4-inch communication conduit encased in concrete through levee 3.0 feet below crown. Sign on both banks of levee. Manhole on both sides of Manthey Rd at utility crossing. (Permit No. 13262, 1981) FS Date: 05/13/2015					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--